




We recommend using hand tools for assembly.
If an electric screwdriver is used, reduce power and torque to avoid damage to the product.









⚠ Caution

Make sure all parts are included. Most board parts are labeled or stamped on the raw edge.
Contact us for a free replacement if you encounter any damaged or missing parts.


Parts List



❶ 4 pcs




❷ 1 pc




❸ 1 pc




❹ 3 pcs




❺ 1 pc



❻ 1 pc



❼ 1 pc







❽ 1 pc




❾ 1 pc

Hardware List

A	X12+1	B	X8+1	C	X5+1	D	X2+1	E	X1	F	X4
											
M6X12 mm		M6X30 mm		M6X35 mm		M6X40 mm		M4X55 mm		M6XØ20 mm	

1


screw down 100%



A	X4	E	X1
M6X12 mm		M4X55 mm	

2


screw down 100%



A	X4
M6X12 mm	

3


screw down 100%



A	X2
	
M6X12 mm	

4


screw down 100%



A	X2
	
M6X12 mm	

5


pre-drill 70%



D	X1
M6X40 mm	


6

pre-drill 70%




D	X1
M6X40 mm	


7



C	X5	F	X4
			
M6X35 mm		M6XØ20 mm	

8



B	X8
	
M6X30 mm	