


















TEIL		MENGE	TEIL		MENGE
A		1	F		1
B		1	G		2
C		1	H		1
D		1	I	 (M8x25)	1
E		1	J	 (M10x25)	4
				 (M10)	
			K	 M4x45	2
			L	 ST5x13	3
			M		1
			N	 	1
			O		1
			P		1
			Q		1
			R		1
			S	 6#	1
			T	 8#	1
			U	 (M8x25)	4
				 (M8)	




1




2




3




4




5




6




7



8




9




DIE BEIDEN C-FÖRMIGEN VERTIEFUNGEN MÜSSEN
IN DIE SELBE RICHTUNG ZEIGEN, DAMIT DIE MONTAGE
ABGESCHLOSSEN WERDEN KANN


13




10




14



11



15



12

