





# SPU 50 Varianto Blocktype

Montageanleitung / Notice de montage / Assembly instruction

Flex-Well Vertriebs  
GmbH & Co. KG  
Industriestr. 80  
32120 Hiddenhausen  
info@flex-well.de





2x 4x





Ø5mm 4x 14x





4x



2x 1x 4x 3,5x15



5x 4x 3,5x30



# US 40 B/ 50 B/ 60 B Variante (Blocktype)

Montageanleitung / Notice de montage / Assembly instruction

Flex-Well Vertriebs  
GmbH & Co. KG  
Industriestr. 80  
32120 Hiddenhausen  
info@flex-well.de

2x 4x

2x 4x

Ø5mm 4x

7x

4x 14x

2x 6x 1x 4x 2x

3,5x15

Ø 5mm


2x 4x 1x 1x

→ ↑ →




2x 2x 4x

Ø8mm



L




R




Ø5mm

8x 8x 12x





L

3x



2x


3x



# H 30 / H 40 / H 50 / H 60 / KH 60-32 / HG 50 / HGH 50 H 50-68 / H 60-68 / H 50-89 / H 60-89 -Varianto

Montageanleitung / Notice de montage / Assembly instruction

Flex-Well Vertriebs  
GmbH & Co.KG  
Industriestr. 80  
32120 Hiddenhausen  
info@flex-well.de



4x




12x

2x


1x

4x

3,5x15



Ø5mm




8x

2x

2x

Ø8mm



4x

