



3x12 mm

A


16x



4 x 12mm

B

6x



4 mm

C

26x



4x25 mm

D

4x



5x50 mm

E

8x



Ø6mm

F

20x



6x35 mm

G

4x



W 6mm

H

4x



W 4mm

I

26x



6 x 50mm

J

12x



K

4x



L

4x



M

16x




N

16x



O

2x




P

11x



Q

11x



R


3x



S 4x



MM 2x



T 2x




U 2x




S1 8x




S2 8x



IA 1x




IB 1x



JB 1x


JA 1x




EE 1x




W 12x





HH 2x



II 2x




CC 2x




BA 2x



BB 2x




DD 2x



LL 2x








KK 1x




2x

1







6

