

## MONTAGEANLEITUNG

-  MONTAGEANLEITUNG
-  ASSEMBLY INSTRUCTION
-  DE INSTRUCTIE VAN DE ASSEMBLAGE
-  ISTRUZIONE DELL'ASSEMBLEA
-  INSTRUCCION DE ASAMBLEA
-  INSTRUCTION DE MONTAGE
-  NÁVOD K MONTÁŽI
-  MONTERINGSANVISNING

-  MONTAJ TALIMATI
-  ASENUSOHJE
-  BRUGSANVISNING
-  BRUKSANVISNING
-  UPUTE ZA MONTAŽU
-  NAVODILA ZA MONTAŽU
-  SZERELÉSI ÚTMUTATÓ
-  INSTRUCTIUNI DE MONTAJ



Modell-Nr.

# 12040

ART.-NR. FRONT KORPUS

12041  Silber

12042  Silber

12044  Silber

12047  Silber

12046  Schwarz

Friedrich Küpper GmbH  
Friedrich-Küpper-Weg  
54570 Berlingen  
Deutschland

Telefon +49 (0) 65 91 - 95 42 0  
Telefax +49 (0) 65 91 - 95 42 17  
E-Mail [info@friedrich-kuepper-gmbh.de](mailto:info@friedrich-kuepper-gmbh.de)  
Internet [www.friedrich-kuepper-gmbh.de](http://www.friedrich-kuepper-gmbh.de)

## EINZELTEILE / PIECES

**A**

**1x**

772 mm x 475 mm



**C**

**1x**

1057 mm x 473 mm



**B**

**1x**


772 mm x 475 mm



**D**

**1x**

1057 mm x 473 mm



**F**

**1x**

645 mm x 450 mm



**E**

**1x**

985 mm x 480 mm



**K**

**1x**


403 mm x 468 mm



**Y**

**1x**


1200 mm x 600 mm



**L**

**1x**

400 mm x 25 mm



**J**

**5x**

450 mm x 120 mm



**X**

**5x**

450 mm x 20 mm



**H**

**5x**


450 mm x 445 mm



**I**

**5x**





470 mm x 130 mm



## BEUTELINHALT / BAG CONTENT

|                                                                                                              |                                                                                                                 |                                                                                                               |                                                                                                             |                                                                                                               |                                                                                                                 |
|--------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|
| <br><b>6x</b><br>5,5 x 19 mm | <br><b>10x</b><br>KU 4 x 16 mm | <br><b>18x</b><br>M5 x 10 mm | <br><b>18x</b><br>ø 5,3 mm | <br><b>18x</b><br>M5       | <br><b>40x</b><br>M4 x 10 mm |
| <br><b>40x</b><br>M4        | <br><b>1x</b><br>M6 x 16 mm    | <br><b>1x</b><br>ø 6,4 mm    | <br><b>1x</b><br>M6        | <br><b>1x</b><br>6 x 12 mm | <br><b>1x</b>                |
| <br><b>1x</b>               | <br><b>1x</b>                  | <br><b>4x</b>                | <br><b>4x</b>              | <br><b>4x</b><br>M8        | <br><b>5x</b>                |

## BENÖTIGTES WERKZEUG / NEEDED TOOLS

|                                                                                                                                                  |                                                                                                                          |                                                                                                           |
|--------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|
| <b>1</b><br><br>PH 1 x 100<br>PH 2 x 100<br>Schlitz 6,5 x 150 | <b>2</b><br><br>SW 7<br>SW 8<br>SW 10 | <b>3</b><br><br>4 mm |
| <b>4</b><br>                                                  | <b>5</b><br>                          | <b>6</b><br><br>5 mm |
| <b>7</b><br>                                                  | <b>8</b><br>                          |                                                                                                           |


1.



## 2. WICHTIG / IMPORTANT



3.  2x M5  2x M5 x 10  2x 5,3 MM



4.




5.  2x M5  2x M5 x 10  2x 5,3 MM  2 SW 8  1 PH 2 x 100



6.




7.




## ZU SCHRITT 4. / IN ADDITION TO STEP 4.


②  SW 8  
①  PH 2x100



## 8. WICHTIG / IMPORTANT



## 9. WICHTIG / IMPORTANT



10.  6x M5  6x M5 x 10  6x 5,3 MM ②  SW 8 ①  PH 2x100



11.  6x M5  6x M5 x 10  6x 5,3 MM ②  SW 8 ①  PH 2x100



12.

4x M8

4x

4x

5



13.


2x M5

2x M5 x 10

2x 5,3 mm

2 SW 8

1 PH 2 x 100



14.



15.  1x  1x 6x12


①  Schlitz 6,5 x 150




16.



17.  1x M6  1x M6 x 16  1x 6,4 mm ②  SW 10 ⑥ 




18.  1x  1x



19.

⑧ ⑦



20.

④ ③



21.

6x 5,5 x 19

② ②  
SW 8 SW 8



22.

①  
5x CR



23.

①  
5x CL




24. 10x M4 10x M4 x 10

② SW7 ① PH1 x 100




25. 30x M4 30x M4 x 10


② SW7 ① PH1 x 100



26.



27.



28.



29.

10x KU 4x16

5x



① PH 2x100



30.





Modell-Nr.

# 12040